


Fracture, Fatigue and Failure of Materials
Professor Indrani Sen
Department of Metallurgical and Materials Engineering
Indian Institute of Technology, Kharagpur
Lecture 57
Failure Analysis- Case Study- Rail Crash

(Refer Slide Time: 0:26)




Hello everyone, welcome back to the 57th lecture of the course Fracture Fatigue and Failure of Materials. And in this module on failure, we are going to discuss about the case studies on rail crash.

(Refer Slide Time: 0:40)




So, let us see what we have in store for this lecture. First of all, we will be discussing about very famous derailment incident for the Intercity Express in Eschede that was in Germany. And of course, we are going to do the failure analysis to find out the actual reason for the failure. This will be followed by another rail crash incident that happened in Hatfield in England. And subsequently the failure analysis will be discussed and the actual root cause for the failure will be more elaborated. And several reasons that can lead to failure for the case of railways will be also discussed such as the rolling contact fatigue spalling and the rail brake will be analyzed.

(Refer Slide Time: 1:26)



So, the first incident happened in 1998. And this is actually considered as the worst high speed rail disaster worldwide. And this happened in Germany at a place called Eschede in Germany.

(Refer Slide Time: 1:47)



Historical Background of InterCity Express

First high speed was introduced by Japan in the 1960s with a maximum speed around 186 mph. Later, other countries like Spain, France also participated in building high speed trains.

Germany came into the running in late 1980's and Deutsche Bahn (German Railway Company) introduced the first luxury high speed train 'Inter City Express (ICE)'.
First locomotive and carriage were delivered in 1989 and 1990 respectively. On 29 May 1991, the ICE network was officially inaugurated and the first generation Inter City Express (ICE 1) trains were on regular schedule since June 1991.

ICE typically runs at ~ 250 km/h.

https://en.wikipedia.org/wiki/Eschede_derailment

NPTEL

So, before we go through the details of the failure incident, let me give you a brief about the Intercity Express and how did we actually land on this. Actually, the first high speed trains were introduced by Japan in the 1960s as known to us, the high-speed trains are considered as the ones which travels at a speed around 186 miles per hour. So that is quite a high value. And later, other European countries are also using such kind of high-speed trains.

And Germany actually came into the picture at around 1980s and Deutsche Bahn, which is the German Railway Company is the one that introduced this kind of high-speed train which is very much a luxurious one as and named that as Intercity Express. So, the first one started on around 1991 it is known as the first generation Intercity Express or ICE 1 and typically this ICE travels at a speed of around 250 kilometer per hour. So, that is quite some high speed.

(Refer Slide Time: 2:58)

Wheel Design

Initially monoblock single cast wheels were used for ICE 1 trains

Monoblock wheel calls for resonance /vibration at cruising speed.

Monoblock single wheel

<https://www.tomawheels.com/post/custom-forged-wheels-monoblock-wheels>

Soon after being deployed, in 1992, a new wheel design (approved by UIC - association for technical cooperation amongst railway) was passed by Deutsche Bahn for the use in their high speed ICE 1 trains after successfully employing it in trams and low speed trains.

NPTEL

And typically, such kind of high-speed trains were initially using monoblock single cast wheels. Here is a picture of the monoblock wheel how it looks like. However, such kind of wheels often leads to the resonance or formation of some vibration at the cruising speed, and that often leads to some kind of turbulence and are not very much favored.

So, later on around 1992 a new wheel design has been employed and such kind of wheel design has been successfully used in trams, and later on has also been employed under high-speed ICE trains.

(Refer Slide Time: 3:40)

Changes in Wheel Design

Monobloc wheels were replaced by new type rubber-sprung resilient wheels for first generation ICE trains, to avoid metal fatigue and vibrations at high speeds.

This wheel design consists of a rubber damping ring in between the rail-contacting steel tyre and steel body

Unfortunately, the new design turned out to be improper, resulting in a failure of one of the rubber sprung dualbloc wheels of ICE 1 (trainset 51, travelling as ICE 884 from Munich to Hamburg) on 3rd June 1998 at a village near Eschede, Germany.

Rubber-Sprung Resilient wheel

<https://ejournal.springeropen.com/articles/10.1186/s10033-019-0383-1>

Web, Rim, Rubber blocks, Mounting ring, Bolt

NPTEL

Now, what exactly is this new wheel design? To understand that, let us look into the picture how it looks different from the monoblock wheels. So typically, this new rubber sprung resilient wheels were used to avoid this vibrations at the high speeds. And this kind of wheel consists of a rubber damping ring in between the rail contacting steel tire and the steel body. You can see the rubber blocks here, which is actually helpful for avoiding the vibration.

However, this kind of new design actually led to the failure of one of the very famous incidents that I am going to discuss, which happened in 1998, at a village near Eschede in Germany. So later on, it has been realized that the design of the wheels are at fault that lead to this catastrophic event.

(Refer Slide Time: 4:35)

The slide, titled "Overview of the incident", provides a summary of the 1998 Eschede train disaster. It features a central photograph of the wreckage, where a high-speed train has derailed and its cars are piled up. Text boxes on the slide state: "Intercity Express collision with a bridge at Eschede, Germany, causing the bridge to collapse along with derailment and rail crash", "101 deaths and almost 200 injured", "Catastrophic emergency was declared leading to utilization of thirty-nine aircrafts, including helicopters and army aircraft for rescue operation", and "1,844 rescuers and 461 ambulance personnel and paramedics." Two URLs are provided: <https://www.dw.com/en/eschede-germanys-worst-train-disaster-remembered-20-years-on/a-44056391> and https://en.wikipedia.org/wiki/Eschede_derailment. The NPTEL logo is visible in the bottom left corner.

So, this Intercity Express, actually collided with a bridge in this place in Germany, when it was leading to a failure of the bridge as well. And along with that around 101 people died as well as almost 200 people were injured in the overall incident. It is considered as a catastrophic emergency and several rescue workers and helicopters and all those rescue operations are being used to save whoever are still alive. So, you can see from this picture here the incident which was quite some catastrophic one and the entire train has been just piled up like a stack of cards.


(Refer Slide Time: 5:23)

Description of the actual reason of failure

Collision of fast moving ICE 884 (travelling at 125 miles per hour) with a stationary vehicle present on tracks was initially thought of as the reason for the accident

Fatigue failure was later identified as the root cause of the incident

One of dual block wheels of 1st carriage failed initially



The outer rim of dual bloc wheel made up of steel broke due to fatigue failure, subsequently leading to deadly sequence of events

Fig:- The broken steel tyre of dual block wheel

Brumsen, Michiel. "Case description: the ICE train accident near Eschede." *European business ethics cases in context*. Springer, Dordrecht, 2011. 157-168.

NPTEL

So, what actually happened on that day is this fast-moving ICE which was named numbered as ICE 884. This is traveling at around 125 miles per hour and it initially got hit by a stationary vehicle and that was considered as a reason for the accident at the very first instance. But later on, after some detailed survey, it was realized that fatigue failure is actually the main reason for this incident. One of the dual block wheels for the first carriage that is the first compartment failed initially and that lead to a series of deadly events one by one.

So, here is the picture of the broken steel tire of the dual block wheel where you can see that how this has been broken from the wheel.

(Refer Slide Time: 6:20)

Chronology of the events

Wheel Fracture

ICE 1 trainset 51 was travelling from Munich to Hamburg route

After stopping in Hanover at 10:30, train continues its journey

About 130 km away from Hamburg and 6 km south of central Eschede , the steel tyre on a wheel on the third axle of the first car got fatally weakened by metal fatigue and failed

It got split and peeled away from the wheel and became flat because of momentum

Finally, it penetrated the floor of the car where it remained embedded.

The tyre embedded in the rail car (coach 1) was seen by one of the passenger and reported to the conductor


Conductor noticed the vibration in coach but due to company policy he needs to investigate the circumstances before applying the emergency brake.

NPTEL

So, wheel fracture is one of the main incidents here. So initially, the trainset 51 was traveling from Munich to Hamburg route. And it after stopping at Hannover at around 10:30 in the morning. It continues its journey while at around 130 kilometers away from Hamburg, and 6 kilometers south of Central Eschede the steel tire on the wheel on the third axle of the first car got fatally weakened by the metal fatigue and failed.

It actually got split and peeled away from the wheel and became flat. So, completely flat because of the momentum. And not only that it penetrated the floor. So, it becomes visible to the passengers actually one of the passengers also noted that it has something has come out from the floor, and he reported that to the conductor of the train. But there were some specific rules for the Deutsche one of the German Railway Company based on which the conductor could not use the emergency brake right away. He needed to understand the situation and investigate the circumstances.

(Refer Slide Time: 7:33)



Chronology of the events

Derailment

As the train passed over the first of two points, the embedded tyre slammed against the guide rail of the points, pulling it from the railway ties.

This guide rail also penetrated the floor of the car, got embedded in the vehicle lifting the bogie off the rails.

The rear axles of car number 3 were switched onto a parallel track, and the entire car was thereby thrown sideways

It passed intact under the bridge and rolled onto the embankment immediately behind it, striking several trees before coming to a stop.

Two Deutsche Bahn railway workers who had been working near the bridge were killed instantly when the derailed car crushed them.

Chronology of the events



Bridge Collapse

The front power car and coaches one and two cleared the bridge.

Coach three hit the bridge, which began to collapse, but cleared the bridge.

Coach four cleared the bridge, moved away from the track onto an embankment

Rest of the coaches derailed and slammed into the pile.

Chronology of the events



Bridge Collapse

The front power car and coaches one and two cleared the bridge.

Coach three hit the bridge, which began to collapse, but cleared the bridge.



Coach four cleared the bridge, moved away from the track onto an embankment

Rest of the coaches derailed and slammed into the pile.

https://www.reddit.com/r/CatastrophicFailure/comments/07p9qg/train_accident_eschede_june_3_1998_the_train/

<https://www.dw.com/en/eschede-germanys-worst-train-disaster-remembered-20-years-on/a-44056391>



So, by the time he was doing that, the derailment already happened. So as the train passed over the first of the 2 points, the embedded tire slammed against the guide rail, pulling it from the railway ties. And this guide rail also penetrated the floor of the car. And this led the vehicle lift from the bogie of the rails. The rear axle of the wagon number 3 is actually switched on to a parallel track and the entire car was there by thrown sideways. As it moved sideways from the track, it actually rolled onto the embankment immediately behind it and striking several trees at the first instance.

And there were 2 Deutsche Bahn railway workers who are working on the nearby locality, they were also crushed by this incident. So, this is not the end of it, the most catastrophic event happened when there was a bridge, and the train has to pass beneath the bridge. And

although the first few coaches cleared the bridge. The fourth coach onward it actually hit the bridge and the rest of the coaches derailed and slammed into the pile.

So, here are the pictures as you can see that this is the broken wheel and these are all the train compartments which are kind of stacked one over the other and the entire bridge also got collapsed. And this is such a huge incident. Almost all the passengers particularly those who are on the backside of the train got severely affected and killed.

(Refer Slide Time: 9:15)




Eschede InterCity Train Disaster



<https://www.youtube.com/watch?v=5LTvnZAR4uU>



Eschede InterCity Train Disaster



<https://www.youtube.com/watch?v=5LTvnZAR4uU>




Eschede InterCity Train Disaster



<https://www.youtube.com/watch?v=5LTvnZAR4uU>



Eschede InterCity Train Disaster



<https://www.youtube.com/watch?v=5LTvnZAR4uU>



NPTEL



Eschede InterCity Train Disaster




<https://www.youtube.com/watch?v=5LTvnZAR4uU>



NPTEL



Eschede InterCity Train Disaster



<https://www.youtube.com/watch?v=5LTvnZAR4uU>



NPTEL



Eschede InterCity Train Disaster




<https://www.youtube.com/watch?v=5LTvnZAR4uU>






Eschede InterCity Train Disaster




<https://www.youtube.com/watch?v=5LTvnZAR4uU>



Eschede InterCity Train Disaster



<https://www.youtube.com/watch?v=5LTvnZAR4uU>



Eschede InterCity Train Disaster



<https://www.youtube.com/watch?v=5LTvnZAR4uU>




Eschede InterCity Train Disaster



<https://www.youtube.com/watch?v=5LTvnZAR4uU>




Eschede InterCity Train Disaster



<https://www.youtube.com/watch?v=5LTvnZAR4uU>




Eschede InterCity Train Disaster



<https://www.youtube.com/watch?v=5LTvnZAR4uU>




Eschede InterCity Train Disaster



<https://www.youtube.com/watch?v=5LTvnZAR4uU>




Eschede InterCity Train Disaster



<https://www.youtube.com/watch?v=5LTvnZAR4uU>




Eschede InterCity Train Disaster



<https://www.youtube.com/watch?v=5LTvnZAR4uU>




Eschede InterCity Train Disaster



<https://www.youtube.com/watch?v=5LTvnZAR4uU>




Eschede InterCity Train Disaster



<https://www.youtube.com/watch?v=5LTvnZAR4uU>




Eschede InterCity Train Disaster



<https://www.youtube.com/watch?v=5LTvnZAR4uU>




Eschede InterCity Train Disaster



<https://www.youtube.com/watch?v=5LTvnZAR4uU>




Eschede InterCity Train Disaster







<https://www.youtube.com/watch?v=5LTvnZAR4uU>




Eschede InterCity Train Disaster







<https://www.youtube.com/watch?v=5LTvnZAR4uU>



Eschede InterCity Train Disaster



<https://www.youtube.com/watch?v=5LTvnZAR4uU>



And here is video to understand what actually has happened. As you can see that while it was traveling at certain speed, this crack moved forward, it broke and then it just penetrated through the floor. And while it was moving at some particular track as it was thrown on the sideways that made it actually hit the bridge. As you can see that it is moving sideways and here comes the bridge which just got hit by the 4th wagon onward as it moves sideways. And you can see how the entire bridge collapsed based on that and suddenly the wagons are also being affected and as we have seen in the pictures they have been just stacked like a pile of cards.

So, this is a simulated one based on the actual reason for failure and you can see that this is such a catastrophic event.

(Refer Slide Time: 10:22)

The slide is titled "Causes of failure" and "Signatures of Fatigue". It contains three text boxes: "Beachmarks (macroscopic) and striations (microscopic) are found in fractured surface.", "Beach Marks are formed when interruptions to crack propagation stage occur, representing the period of time over which crack growth occurred", and "Striations represent the advance distance of the crack front during a single load cycle." Below the text are two images: a macroscopic view of a fracture surface with a red arrow pointing to a "Fatigue" crack origin, and a micrograph showing "Fatigue crack origin" with a red arrow. A small inset image shows a person in a yellow shirt. The slide footer includes the NPTEL logo and a citation: "Esslinger, Volker, et al. 'The railway accident of Eschede-technical background.' *Engineering Failure Analysis* 11.4 (2004): 515-535."

So, when the detailed investigation has been made to find out the actual reason for the failure, it has been noted from the failed surfaces that there are some formation of beach marks that has been noted at quite low magnification as well as the high magnification investigation of the fractograph shows the presence of striation we have already discussed in details in module 2 about the fatigue behavior and there we have seen that such kind of Beach Marks are formed when the interruptions to the crack propagation stage occur.

And this represent the period of time over which the crack has grown and this is also reflected in the presence of striations, which actually signify the advancement of the crack front during a single load cycle. So, each of distraction with signify that and here are the pictures where you can see this kind of rings very clearly from the microstructures and this suddenly signifies the reason as fatigue.

So, fatigue failure must have occurred, if we look into this very carefully, you will be able to note this semicircular point here, which signifies actually the crack initiation point. So, that those are the indications that fatigue must have been the actual reason that the tire broke at the very first place.

(Refer Slide Time: 11:49)

Issues linked with catastrophic failure

Poor Operational Testing/Inspection Procedures

- No efficient methods for detecting micro level cracks other than Ultrasound equipment
- The engineers used to check the macro level cracks with a flashlight.
- No equipment to perform complete fatigue test of the large components at that time.

The slide features a blue header with the title, a yellow sub-header, and a white background with faint technical icons. A presenter is visible in the bottom right corner. The NPTEL logo is at the bottom left.

So, the signatures of fatigue were something very important to notice. And typically, this rubber sprung wheels are used in place of the monoblock cast wheels as discussed right to overcome the problem of noise and vibration at high speed. However, the cyclic loading caused the inner wheel to wear out which subsequently weakened the already the thin out of tire. The low thermal expansion coefficient of the rubbers now that is a difference between a rubber as well as a metal. The tire typically is made of metal, but this rubber one is having quite low thermal expansion coefficient. And that lead to less expansion on heating, whereas more stress is there on the wheel tire.

And suddenly this kind of new design, although were fine for trams for which it has been tested and has been quite in practice. But when it came to the high-speed rail, this actually led to the fatigue failure to occur and that led to the whole catastrophic incident. So, this design of the double block rubber sprung wheels are not suitable for such kind of high-speed trains.

(Refer Slide Time: 13:00)

Issues linked with catastrophic failure

Poor Operational Testing/Inspection Procedures

- No efficient methods for detecting micro level cracks other than Ultrasound equipment
- The engineers used to check the macro level cracks with a flashlight.
- No equipment to perform complete fatigue test of the large components at that time.

Issues linked with catastrophic failure

Strict Company Policy

- Emergency brakes could only be applied after the conductor viewed the damage.
- Several minutes wasted between the time the tyre broke and the actual accident.
- Conductor was about to see the damage in first carriage, when the train collided into the bridge.

Poor Bridge Design and Set Point Location

- The Bridge was not supported by strong piers. (just 2 thin pillars)

Not only that, there is some poor operational or inspection procedures at that time as well. So, there were actually no efficient methods for detecting micro level cracks as we have discussed that often, such kind of structures need to be continuously monitored or monitored after a certain period of time to see whether there has been any crack that has been formed during the process. And this has typically been done by the ultrasound equipment, but that was not sufficient to detect the presence of any such crack.

The engineers used to check the macro level cracks with the flashlight. Again, that is not very much appropriate but no equipment to perform complete fatigue tests of the large components were not seriously considered at that time.

Not only that, there were some strict company policies that also plays hand in hand to have this catastrophic incident for instance, emergency brakes could not be applied. So, there was a company policy or rule that emergency brakes cannot be used unless there is a serious incident and for to understand that whether the matter is serious or not, that needs to be investigated first.

So, of course, there was not enough time for that and several minutes were actually wasted to understand the severity of the process. And by that time, it got hit by the bridge and everything collapsed. Not only that, the bridge design was also poor, it was not supported by strong piers rather, there was just 2 thin pillars over which the entire bridge was structured.

(Refer Slide Time: 14:40)

The slide features a blue header with the title "Steps taken to avoid such failures in future". Below the title, four white boxes with black text list the following steps:

- Replaced back to monoblock wheels.
- Mandatory testing before developing a new design.
- Changing wheels before reaching the fatigue limit.
- Avoiding structural irregularities, eliminating sharp changes along the edges that lead to square edges will lead to a higher fatigue strength.

In the bottom right corner, there is a small video feed of a woman with glasses wearing a yellow top. The slide also includes decorative gear icons and the NPTEL logo at the bottom left.

Now after this incident has happened, as I mentioned, this is still considered as the worst rail crash worldwide. So, of course there were several steps that were taken to avoid such failures in future and first of all, the monoblock wheels are being used once again. And then there was mandatory testing before developing any new design and changing wheels before the fatigue limit has been reached.

So, there comes the importance of safe life design where the life period of the wheels and the axels as well as the tracks, railway tracks are all estimated and then there has been thorough investigation to understand whether there has been any cracks generated in the process and then that needs to be replaced even if there no cracks has been found but still if it has exceeded the safe life period.

And avoiding structural irregularities, eliminating sharp changes along the edges that lead to square edges, that may lead to higher fatigue strength are been typically used.

(Refer Slide Time: 15:49)

Steps to prevent fatigue failure

- Improve the surface finish by polishing, to prevent small scratches or grooves that appear on a part's surface due to cutting
- Increase performance by means of residual compression stress on a thin surface layer.
- Rolling and Shot peening provide the necessary residual compressive stress layer

Micro-polishing of crankshaft

<https://www.pontiacdly.com/pontiac-v-8-crankshaft-performance-guide/>

The slide features a blue header with the title 'Steps to prevent fatigue failure'. Below the title are three text boxes containing the listed steps. A photograph shows a crankshaft being polished by a blue abrasive belt. A URL is provided below the photo. The slide also includes a small video inset of a woman in a yellow shirt and the NPTEL logo at the bottom left.

Now, what could have been done to prevent the fatigue failure is the surface finish could have been improved and this is what is being practiced these days. So, the surface finish is improved by polishing to prevent small scratches or groups that appear on the surface or there would have been residual compressive layer that is formed typically by rolling or short painting that enhances the fatigue strength of the material as discussed in the module for fatigue. So, this is one example of micro polishing of crankshaft to enhance the life of that structure.

(Refer Slide Time: 16:29)

Memorial for the victims

- Memorial built by Udo Bauch (A survivor of the accident) by his savings
- Official memorial site next to the bridge, with the railway line in the background
- official memorial, funded partly by Deutsche Bahn has engravings of 101 victims

https://en.wikipedia.org/wiki/Eschede_derailment

The slide has a blue header with the title 'Memorial for the victims'. It contains three photographs: a small white building, a railway bridge over a green field, and a stone memorial wall. Each photo has a corresponding text description below it. A URL is at the bottom center. The slide includes a small video inset of a woman in a yellow shirt and the NPTEL logo at the bottom left.

So, here is the memorial for the victims that has been built in honor of the Eschede rail crash.

(Refer Slide Time: 16:36)

Rail Crash at Hatfield (2000)

Ref: <https://www.bbc.com/news/uk-england-beds-bucks-herts-54568464>

Rail Crash at Hatfield

Train Name: Great North Eastern Railway (GNER) InterCity 225

17 Oct 2000, At 12:10 Travelling from London King's Cross to Leeds

Train Speed = 115 mph or 185 km/h

Derailed at south of Hatfield station at 12:23

Train travelled a further 1000 yards or 910 m after derailment

Leading locomotive engine and first two coaches remained upright and the trailing coaches were derailed

Ref: https://en.wikipedia.org/wiki/Hatfield_rail_crash

So let us move on to another incident that happened just after 2 years at Hatfield that is in England. So here also you can see that the rail has been derailed from its actual track. And basically, this is once again an Intercity Express, Intercity 225 are a great North Eastern Railway. And this incident happened and on 17th of October 2000, while the train was traveling from London's King's Cross to Leeds. It was traveling at a speed of 185 kilometer per hour and it actually derailed at the south of Hatfield Station at around 12:23. After derailment happened, it also traveled farther for around 900 meter and leading to locomotive engine and the first 2 coaches that remain upright and the trailing coaches were actually derailed.

(Refer Slide Time: 17:33)

Hatfield Railway Crash Accident

The whole train segmented into three sections resulting in severe damage

This whole incident occurred in around 17 seconds

Out of 170 passengers, Four passengers died and 33 were initially injured which later raised to over 70

Ref: https://en.wikipedia.org/wiki/Hatfield_rail_crash

Ref: The scene near Hatfield in Hertfordshire after a high speed train derailed (Image: Stefan Rousseau/PA Wire)

NPTEL

Preliminary Investigation

Cause of the accident

Found a broken rail at the place of incident

Reason: "Rolling Contact Fatigue"

Cracks are caused by high load where the wheels of train get in contact with the rails

Due to repetition in loads, the fatigue crack initiates and grows at faster rate

Crack reaches a critical size and finally failure of rails take place catastrophically

Ref: https://en.wikipedia.org/wiki/Hatfield_rail_crash

NPTEL

So, the entire structure of the entire whole train actually segmented into three sections resulting in severe damage, this whole incident happened just within 17 seconds. Now, here the casualties are much less compared to the previous incident. So, out of 170 passengers, only 4 passengers died reportedly and 33 were initially injured, which later the number came to around 70, but still the numbers were quite less than the Eschede train rail crash. However, when we come to the cause for the accident, a broken rail was found at the place of the incident which has been severely examined and the reason for the failure has been considered as a rolling contact fatigue.

Now, this is a very common phenomenon that happens that is a very much significance particularly for railway tracks. So, what happens is that the cracks are caused by the high load

where the wheels of the train get in contact with the rails. So, there are the rail tracks and there comes the wheel. So, at this point of contact at this point here, which happens repeatedly. So, once the wheel turn and then again comes back here. So, this point of contact, which actually is all throughout the wheel structure, this leads to generation of fatigue crack initiation.

And due to the repetition in loads the fatigue crack initiates and grows at a very faster rate. Once it reaches a critical size, final failure often occurs in a catastrophic manner.


(Refer Slide Time: 19:13)

The slide, titled "Cause of Rail defects", explains that rails are subjected to severe stresses from heavy freight traffic, high-speed trains, and constant braking and acceleration. It notes that in addition to natural wear, spalling and railbreak may occur. The slide includes four diagrams: "Small Cracks", "Growing cracks", "Loss of Material Spalling", and "Railbreak". It also features two photographs: "Rail spalling" and "Rail Break". A video inset shows a woman speaking. The slide includes two references: Kapoor A., Salehi L., Ash A.M.S. (2013) Rolling Contact Fatigue (RCF). In: Wang Q.J., Chung Y.W. (eds) Encyclopedia of Tribology. Springer, Boston, MA. https://doi.org/10.1007/978-0-387-92897-5_287 and Wang, Kaiyun, et al. "Numerical investigation on wheel-rail dynamic vibration excited by rail spalling in high-speed railways." *Shock and Vibration* 2016 (2016). The slide also features the NPTEL logo.

So, the same thing happened here also, along with that, there are some other reasons, which are typically found as the rail defects such as the rails are subjected to severe stresses from heavy freight traffic, high speed trains and constant braking and acceleration of railway. So, because of these fluctuations in the load levels also, along with the natural wear, spalling and rail break may occur.

So, let us see what do we mean by this incident. So, the top of the rails often leads to formation of some small cracks, which then keeps on growing and that may lead to some loss of the materials. So, this entire part gets eroded up and that is known as a spalling or it may lead to the rail break. So, you can see the pictures here for spalling where the parts come out and the rail break where the entire rail track actually breaks because of this kind of damage.

(Refer Slide Time: 20:13)



So, here are again the different types of rail contact fatigue defects that may occur. Rail gauge corner cracking, you can see the cracks that are developing here the thin cracks appearing on the gauge corner of rails and this typically develop as a result of high rail to real contact stress. Large shear stress between the slip of the wheels and rails. They can be shelling also as you can see, the material can get chipped off from the structure and this kind of large chunks of metals are coming out and certainly if such kind of irregularity are formed on the tracks.

These are not a good news these are the sources for a lot of damage to occur. For example, let us say fatigue damage and that lead to the overall failure of the rail track. This is the example of squats were the surface defects associated with high-speed trains. This is nothing but shallow depression, as you can see here. So, not like the entire part is being chipped off as we are seeing for the case of shelling. But in this case, there is actually a subsurface cracking and that leads to once again irregularity in the surface structure leading to the early sensation of fatigue cracks.

(Refer Slide Time: 21:33)

Cause of Rail defects in Hatfield railway Crash

Numerous fatigue cracks were identified by reassembling the broken portions and it contributed to the spalling of the running surface about 5 mm deep and 100 mm long.

This problem was known before the incident.

A letter from the construction maintenance company Railtrack in December 1999 warned that railtrack line specification is insufficient to guard against this type of fatigue.

The replacement tracks were manufactured but those were not delivered at the right place.

Ref: https://en.wikipedia.org/wiki/Hatfield_rail_crash

NPTEL

So, in case of the Hatfield railway crash numerous fatigue cracks were identified by when investigated the broken portions and it contributed to the spalling of the running surface about 5 millimeter deep and 100 millimeter long. So, that is quite some length, which actually has led to the fracture. This problem has been known before the incident actually happened and there was a provision to change the rail track however, the replacement tracks was not delivered at the right place at the right time and that leads to this severe incident.

(Refer Slide Time: 22:09)

After the incident


After that Railtrack has imposed emergency speed restrictions and instigated a costly nationwide track replacement programme.

Ref: https://en.wikipedia.org/wiki/Hatfield_rail_crash

NPTEL


After the incident

After that Railtrack has imposed emergency speed restrictions and instigated a costly nationwide track replacement programme.



An Intercity 225 passing a memorial garden for the crash victims

Ref: https://en.wikipedia.org/wiki/Hatfield_rail_crash



So, after the rail track has imposed several procedures to avoid such kind of incidents in future. For example, emergency speed restrictions were imposed, and a costly nationwide track replacement program has been instigated all throughout. Here is the memorial for the Intercity 225.

(Refer Slide Time: 22:35)


CONCLUSION

Great North Eastern Railway (GNER) InterCity 225 train segmented into three

Broken rail owing to fatigue is the main cause for the accident of the train.


Rolling contact fatigue cracks are caused by high load where the wheels of train get contact with the rails

Spalling, rail break, rail gauge corner cracking, shelling etc. are different types of defects observed due to rail contact fatigue.




REFERENCES

https://en.wikipedia.org/wiki/ICE_1
https://en.wikipedia.org/wiki/Eschede_derailment
<https://www.lomawheels.com/post/custom-forged-wheels-monoblock-wheels>
<http://www.inforta.lt/EN/products/product/25/resilient-wheels/>
https://www.reddit.com/r/CatastrophicFailure/comments/l7pqvg/train_accident_eschede_june_3_1998_the_train/
<https://www.dw.com/en/eschede-germanys-worst-train-disaster-remembered-20-years-on/a-44056391>
<https://cjme.springeropen.com/articles/10.1186/s10033-019-0383-1>
 Smith, R. A. "Railway fatigue failures: an overview of a long standing problem." *Materialwissenschaft und Werkstofftechnik: Entwicklung, Fertigung, Prüfung, Eigenschaften und Anwendungen technischer Werkstoffe* 36.11 (2005): 697-705.



REFERENCES

https://en.wikipedia.org/wiki/ICE_1
https://en.wikipedia.org/wiki/Eschede_derailment
<https://www.lomawheels.com/post/custom-forged-wheels-monoblock-wheels>
<http://www.inforta.lt/EN/products/product/25/resilient-wheels/>
https://www.reddit.com/r/CatastrophicFailure/comments/l7pqvg/train_accident_eschede_june_3_1998_the_train/
<https://www.dw.com/en/eschede-germanys-worst-train-disaster-remembered-20-years-on/a-44056391>
<https://cjme.springeropen.com/articles/10.1186/s10033-019-0383-1>
 Smith, R. A. "Railway fatigue failures: an overview of a long standing problem." *Materialwissenschaft und Werkstofftechnik: Entwicklung, Fertigung, Prüfung, Eigenschaften und Anwendungen technischer Werkstoffe* 36.11 (2005): 697-705.



So, what we understand from these two rail crash is that the derailment of high speed Intercity Express and collapse of the bridge near Eschede, Germany was the worst real failure worldwide. The fracture of the wheel tire that brought the accident of ICE 884 this actually happened because of the formation of a fatigue crack and which finally propagated at a relatively low mean stress due to the reduced cross section of the tyre.

The collision of the bridge and its collapse actually made it a catastrophic incident with the total death toll of around 101. Now some ways to improve the fatigue performance and the fatigue strength of such kind of structure would be rolling and shot peening to generate the residual compressive stress layer that may improve the performance of the structure.

In case of the Hatfield incident, which happened for the Great Northeastern Railway, Intercity 225 actually the train has been segmented into 3 broken rails owing to the fatigue is

once again found as the main reason for the failure. So, for both the cases we are seeing that fatigue failure is very much relevant and is of high concern for the case of the railway. Rolling contact fatigue cracks are caused at high load where the wheels of the train get in contact with the rails and that is one of the very important causes that may lead to such kind of catastrophic failure.

The other reasons that could lead to rail defects are spalling or rail brake or rail gauge corner cracking, shelling etc, are different types of defects observed due to the rail contact fatigue. So, following the references for both two case studies and thank you very much.